ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	1	Kempegowda Ward
Street ID	**Street Name**	**Significant Landmark**
W0138, W0132, W0175, W0152, W0154, W0179, W0183, W	2nd Crs, NA	Maruthi nagar
Segment No.	**Total Length (m)**	
1/C-W0138/S011834	39.14	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	5.08	77.607905	13.108556	77.607950	13.108546	W0179	W0179
2	6.34	77.608236	13.109272	77.608263	13.109322	W0154	W0154
3	7.18	77.607689	13.109964	77.607720	13.110021	W0150	W0150
4	6.99	77.607563	13.109707	77.607590	13.109764	W0152	W0152
5	7.38	77.607524	13.109712	77.607556	13.109771	W0152	W0152
6	6.17	77.606082	13.111063	77.606138	13.111055	W0132	W0132

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of Culverts in Maruthi nagar in ward no 01 Yelahanka Sub-Division Yelahanka zone	850000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	CULVERTS
Tender	**Work Details**	**Job No. / Work Code**
Tender	Construction of Culverts in Maruthi nagar in ward no 01 Yelahanka Sub-Division Yelahanka zone	001-16-000006
Work Order No.	**Work Order Date**	**Period of Extention**
EE(YNK.D)/E-PMT-1/WO/01/2015-16	24/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
24/02/2016	23/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

S VASU

0.00

Phone No.	E-Mail ID
9902911262	

Field Inspection Details

Number of Trees	Any Other Information	Name
0		CHANDRASHEKAR
Date of Inspection	**Remarks**	
03/12/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0138, W0132, W0175, W0152,

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	03/12/2016	02/01/2017	COMPLETED
SE	VASU K M	03/12/2016	02/01/2017	COMPLETED
EE	VASU K M	03/12/2016	02/01/2017	COMPLETED
AEE	G.B. PRABHAKAR	03/12/2016	02/01/2017	COMPLETED
AE	CHANDRASHEKAR	03/12/2016	02/01/2017	COMPLETED
AE	CHANDRASHEKAR	03/12/2016	02/01/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0138, W0132, W0175, W0152,